




## RELOCATION – EXTERNAL POWER RECEPTACLE

### ADVANTAGES

- LOW COST
- EASY TO INSTALL
- REDUCED RECURRING MAINTENANCE
- **NO AOG'S**

### APPLICABILITY

DASH 6      TWIN OTTER  
ALL SERIES



## DESCRIPTION

### **PROBLEM – SOLVED!!!!**

Erwin Aero International Ltd. can save you time and money when you re-locate the existing External Power Receptacle and the Battery Relays above the cargo compartment floor!

This STC solves two major problems with DHC – 6 aircraft; the ingress of water through the OEM door, and it eliminates the need to remove the cargo floor to complete the External Power and Battery Relay inspection (ref. PSM 1-6-7 CH 24 No. 16). Floatplane Ground Handlers like this modification because it increases the height of the door eliminating the need to bend to hook up external power.

The kit includes the installation parts, and all the necessary hardware.

**Contact - Erwin Aero International Ltd. 011 1 403 948 7306  
FOR A PRICE QUOTE!**

### MANPOWER

- Estimated 44 hours / Installation

### CERTIFICATION

- Transport Canada STC No. **SA06-80**
- FAA STC No. Pending
- EASA STC No. Pending